Sanitized Copy Approved for Release 2010/04/15 : CIA-RDP58-00453R000300020032-6

25 YEAR RE-REVIEW

TAB

STAT	17 Sostander 1
	Ricotrical North - Tespo J Building
	It is kindly requested that the electrician install a two- way busser system between rooms 2002, 2004 and 2006 Tampo & Build- ing, in accordance with the attached electric
	Those busters are required for use in convection with the telephones and should be installed as seen as possible.
STAT	should be one acted for portheaut detail.
	Charan be our arter now data